

Before using the support software, please check the following precautions.

1. Precaution for operating Environment

If there are no following software on your computer, installation of the support software would not be proceeded.

Note: Please sign in by administrative account.

[Operating System]

- Windows XP SP3 or higher
- Windows Vista SP1 or higher
- Windows 7

[Required Software]

- Microsoft .NET Framework Version 4.0
- USM-S485 converter

[Installing Software]

- Microsoft .NET Framework Version 4.0
—dotNetFx40_Client_x86_x64.exe
- USM-S485 converter
—CDM20814_Setup.exe

2. Precaution for installation

- 2-1. Under required environment, please download [dotNetFx40_Client_x86_x64.exe].
- 2-2. After downloading, run the file [dotNetFx40_Client_x86_x64.exe].
- 2-3. Installation of [Microsoft .NET Framework Version 4.0] will start.
- 2-4. Please download [CDM20814_Setup.exe].
- 2-5. After downloading, run the file [CDM20814_Setup.exe].
- 2-6. Installation of [USM-S485] converter will start.
- 2-7. Please download [IBFL_TC_SupportSoft_Ver.1.00.zip], the support software for configuring IBFL-TC.
- 2-8. After downloading, run [IBFL_TC_SupportSoft_Ver.1.00.zip], and unzip it in any folder. After unzipping, run [IBFL_TC.exe] to boot up the support software for configuring IBFL-TC.

*These software specifications are subject to change without notice.

*This software may not be edited, sold and rented without permission of KOGANEI CORP.

*KOGANEI CORP. shall in no way be liable or responsible for injuries or damages to persons or property arising out of the use or operation of the software.